Requests:

of the drawing, please make the proposed changes, based on the following:

(1) Add to the case 8, the support stock on the outside of the said case 8; along / around the axles 5, and 10.

Otherwise, the case 8, would have to be supported in the housing 25, (shown fragmented) on the axles 5, and 10. This would be possible, but not practical

(2) Add lines of invisibility where axle 5, passes through the support stock of the bevel gear 12.

Herein indicating that the bevel gear 12, and the axle 5, are splined / stationary; to each other.

This correction can be justified, by the "Detailed Description of the Drawing". See; lines 5, and 6, saying; "A bevel gear 12; being splined to axle shaft 5".

- (3) Add hatching lines to the support stock of case 9, and other informalities of the hatching lines; where indicated.
- (4) Make the indicated changes of the reference numbers; whether added or changed.

Thank You!